



Exploded

E7063 SMITH MACHINE

please note :prats didn't demolitionde
part and fast eners not listde on
theintroduction



A35	Spring washer Φ12	8
A34	Flat washer Φ12	8
A33	Outside hex screw M12*35	8
A24	Spring washer Φ10	4
A23	Flat washer Φ10	4
A22	Outside hex screw M10*20	4
A21	Spring washer Φ10	16
A20	Cap head inner hex screw M10*16	16
A9	Spring washer Φ10	12
A8	Flat washer Φ10	12
A7	Outside hex screw M12*35	12
A6	Spring washer Φ10	4
A5	Flat washer Φ10	4
A4	Cylindriacal head screws M10*25	4
03	Connection	1
02	Parallel bars group	1
01	Main frame	2
No.	Name	Qty